


TIP OF LEAF
IS PAST BUILDING



LEAF SHOULD
CLIP CORNER
OF BUILDING